



NOTES:
1. REPAIR EXISTING EXTERIOR WALLS AS SHOWN. PATCH ASPHALT WHERE DOCK LEVELERS WERE REMOVED.
2. REPAIR EXISTING FLOOR WHERE DOCK LEVELERS WERE REMOVED.

FIRST FLOOR PLAN
1/8" = 1'